

Tables

Table 1 - Standard Ranges

Scale Ranges(° C)	Measuring Ranges(° C)	Scale Resolution(°C)
-30/+50	-20/+40	0.5
-20/+60	-10/+50	0.5
0/60	+10/+50	0.5
0/80	+10/+70	0.5
0/100	+10/+90	1
0/120	+20/+100	1
0/160	+20/+140	1
0/200	+20/+180	2
0/300	+30/+270	2
0/400	+50/+350	5
0/500	+50/+450	5
0/600	+50/+550	5

Table 2 - Connections

Code	Connection Type
P	Plain Stem
M	Male Nut
U	Union Nut
AM	Adjustable Male
AU	Adjustable Union

Table 3 - Options

Code	Description
0	None
1	Liquid Filling
2	Hermetic Sealing as per ASME B40.3
3	Shatter-Proof Glass
4	Stainless Steel tag plate
5	Alarm Contacts (SPST or SPDT)
6	Special Requirement.